

Work Order ID 73752-1

Wednesday, September 14, 2011 2:47:47 PM

Page 1

Item ID: K10003

Revision ID:

Item Name: Saddle, D205-634-011

Start Date: 9/14/2011 Start Qty: 6.00

Required Date: 9/19/2011 Req'd Qty: 6.00

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

IIN634,635

Rev F

100



DC

Document Control

DOCUMENT CONTROL

Memo

Create White labels only per PPP K10003

0.00

0.00

CHG 007

S w l u l y

HA for MLJ 11-9-28

110



Packaging

Packaging

Pick Kit

Memo

0.00

0.00

SP 11-11-10

120



QC

Quality Control

QC4- 100% Inspect kits for completeness

Memo

0.00

0.00

S w l u l y

(x4)

Work Order ID 73752

Wednesday, September 14, 2011 2:47:47 PM

Page 2

Item ID: K10003

Accept

Revision ID:

Setup Start

Item Name: Saddle, D205-634-011

Stop

Start Date: 9/14/2011 Start Qty: 6.00

Required Date: 9/19/2011 Req'd Qty: 6.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

130

Identify as per dwg & Stock Location: _____

0.00

Packaging

Memo

0.00

Packaging

140

QC21- Final Inspection - Work Order Release

0.00

QC

Memo

0.00

Quality Control

11/11/14
mr
11-11-14

Picklist Print

Wednesday, September 14, 2011 2:47:44 PM

Page 1

Work Order ID: 73752

Parent Item: K10003

Parent Item Name: Saddle, D205-634-011



Start Date: 9/14/2011

Required Date: 9/19/2011

Start Qty: 6.00

Required Qty: 6.00

Comments: IPP: 11.03.01.16 Reformat: Incorporated D205-641-011 KJ/RF
 IPP: J 06-07-25 As per DSI 9344 JLM
 IPP: K 06.11.17 Per K10003 Rev C KJ
 IPP: L 07.01.12 Document Record for copying bluefile rmv KJ
 IPP Rev:M 08-08-12 now @ chg 006 (DSI 9418) DD verified by:
 IPP N 09.01.27 DSI 9418 rev B EC verified by: DD IPP Rev:O
 11.03.11 per dsi9536 DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

AN4-51A



Bolt

Purchased

No

110

Each

149.0000

8

48

Location

Loc Qty

Loc Code

ST361

149

118451

49

118628

50

118706

50

AN4-6A



Bolt

Purchased

No

110

Each

1,216.000

16

96

Location

Loc Qty

Loc Code

ST356

1200

117872

200

118422

300

118628

400

118838

300

ST358

16

117514

16

m11912754x.

Picklist Print

Wednesday, September 14, 2011 2:47:44 PM

Page 2

Work Order ID: 73752

Parent Item: K10003

Parent Item Name: Saddle, D205-634-011

Start Date: 9/14/2011

Required Date: 9/19/2011

Start Qty: 6.00

Required Qty: 6.00

AN4C46A
BOLT

Purchased No

110 Each 57.0000

4 24



SP

Location

Loc Qty

Loc Code

ST360

57

110823

7

118758

50

110 Each 91.0000

8 48



7x

SP

AN6-12A
Bolt

Purchased No

Location

Loc Qty

Loc Code

ST342

91

118706

41

118838

50

110 Each 0.0000

32 192



4x

SP

AN960JD416
Washer

Purchased No

AN960JD616
Washer

Purchased No

110 Each 0.0000

8 48



m119097 SP

SP

D2570
Bushing

Manufactured No

110 Each 133.0000

24 144



m119075 SP

373753 SP 11-11-10

Location

Loc Qty

Loc Code

ST017

133

66933

1

67759

6

72122

1

73636

125

Wednesday, September 14, 2011 2:47:44 PM

Shop Packet Print

Page 2

Picklist Print

Wednesday, September 14, 2011 2:47:44 PM

Page 3

Work Order ID: 73752

Parent Item: K10003

Parent Item Name: Saddle, D205-634-011

Start Date: 9/14/2011

Required Date: 9/19/2011


Start Qty: 6.00

Required Qty: 6.00

S D2571
Saddle, Fwd Out 205

Manufactured No

110 Each 13.0000

LI 6


SP 1X Ce
73705

Location

Loc Qty

Loc Code

ST433

13

72340


1

72969

12

Manufactured No

110 Each 10.0000

3x
6


B73683

Location

Loc Qty

Loc Code

ST433

10

71107

2

72968

8

Manufactured No

110 Each 11.0000

6


B73682 SP 11-11-14

Location

Loc Qty

Loc Code

ST434


11

72936

11

Manufactured No

110 Each 9.0000

6


B73684 SP 11-11-14

Location

Loc Qty

Loc Code

ST434

9

72937

9

S D2573
Saddle, Aft Out 205

S D2574
Saddle, Aft In 205

Wednesday, September 14, 2011 2:47:44 PM

Shop Packet Print

Page 3

.Picklist Print

Wednesday, September 14, 2011 2:47:44 PM

Page 4

Work Order ID: 73752

Parent Item: K10003

Parent Item Name: Saddle, D205-634-011

Start Date: 9/14/2011

Required Date: 9/19/2011

Start Qty: 6.00

Required Qty: 6.00

D2747
Set Screw

Manufactured No

110 Each

150.0000



4 24

SP

Location

Loc Qty

Loc Code

ST021

150

71163

50

73495

100

Manufactured No

110 Each

35.0000



2 12

24x

SP

Location

Loc Qty

Loc Code

ST025

35

72136

35

Manufactured No

110 Each

35.0000



2 12

12x

SP

Location

Loc Qty

Loc Code

ST025

35

72135

35

Manufactured No

110 Each

7.0000



1 6

12x

B 73338 SP

Location

Loc Qty

Loc Code

ST423

5

70980

5

ST474

2

62227

2

Wednesday, September 14, 2011 2:47:44 PM

Shop Packet Print

Page 4

Wednesday, September 14, 2011 2:47:44 PM

Page 5

1. The first step in the process is to identify the problem. This involves gathering information about the situation and understanding the needs of the stakeholders involved.

2. Once the problem is identified, the next step is to develop a plan. This involves setting goals, identifying resources, and determining the steps that need to be taken to solve the problem.

3. The third step is to implement the plan. This involves putting the plan into action and monitoring progress to ensure that the goals are being met.

4. Finally, the fourth step is to evaluate the results. This involves assessing the effectiveness of the plan and making adjustments as needed to improve the outcome.

[illegible]

Required Date: 9/19/2011

Required Qty: 6.00

110	Each	2.0000
-----	------	--------

Lug Assembly

110	Each	2.0000
-----	------	--------

Loc Code

110	Each	9.0000
-----	------	--------



Tow Ring

110	Each	9.0000
-----	------	--------

Loc CodeLoc Code

110	Each	12,0000
-----	------	---------

[illegible]

Washer

110	Each	12,0000
-----	------	---------

Loc Code

110	Each	139.0000
-----	------	----------

[illegible]

Washer

110	Each	139.0000
-----	------	----------

Loc Code

Loc Code

Shop Packet Print

Page 5

Picklist Print

Wednesday, September 14, 2011 2:47:45 PM

Page 6

Work Order ID: 73752

Parent Item: K10003

Parent Item Name: Saddle, D205-634-011



Start Date: 9/14/2011

Required Date: 9/19/2011

Start Qty: 6.00

Required Qty: 6.00

D3533-1
Set Screw

Manufactured No

110 Each

96.0000



2 12

SP

Location

Loc Qty

Loc Code

ST066

96

73310

96

Purchased No

110 Each

3,589.000



24 144

m 118927 SP.
144x.

MS21042L4
Nut

Location

Loc Qty

Loc Code

ST300

3589

117441

51

117601

637

117885

901

118451

2000

Purchased No

110 Each

1,292.000



5 30

SP 11-11-10.

MS21043-4
Nut

Location

Loc Qty

Loc Code

FG

40

104603

40

ST301

1252

117793

472

118378

280

118686

500

SP

Wednesday, September 14, 2011 2:47:45 PM

Shop Packet Print

Page 6

5.0 PARTS LIST

Item	634 -011	634 -015	634 -041	634 -045	641 -011	Part Number	Description
	X					D205-634-011	SKIDTUBE INSTALLATION (STANDARD)
		X				D205-634-015	SKIDTUBE INSTALLATION (MODIFIED)
	1		X			D205-634-041	SKIDTUBE
		1		X		D205-634-045	SKIDTUBE
	1	1			X	D205-641-011	GROUND HANDLING KIT
1			1			D2580-041	205 SKIDTUBE ASSEMBLY (STANDARD)
1				1		D2580-045	205 SKIDTUBE ASSEMBLY (MODIFIED)
2A			16	16		D2594-1	* PLUG
2B			16	16		D2594-3	* O-RING
3			1	1		D2855	* AFT CAP
4			2	2		AN3-5A	* BOLT
5			2	2		NAS1149D0332J	* WASHER (AN960JD10L)
6A			1	1		D3564-9	* WEARSHOE (REPLACES D2577-1)
6B			1	1		D3566-1	* GASKET
7A			1	1		D3564-11	* WEARSHOE (REPLACES D2577-3)
7B			1	1		D3566-1	* GASKET
8A			1	1		D3564-5	* WEARSHOE (REPLACES D2577-5)
8B			1	1		D3566-5	* GASKET
9A			1	1		D3564-13	* WEARSHOE
9B			1	1		D3566-13	* GASKET
10			50	50		AN3C4A	* BOLT (REPLACES AN3-4A)
11			50	50		NAS1149C0332R	* WASHER (AN960C10L)
12			50	50		ALS4-1032-130	* INSERT
13			2	2		ALS4-1032-225	* INSERT
20	1	1				D2571	SADDLE, FWD OUTSIDE
21	1	1				D2572	SADDLE, FWD INSIDE
22	1	1				D2573	SADDLE, AFT OUTSIDE
23	1	1				D2574	SADDLE, AFT INSIDE
24	8	8				AN4-51A	BOLT
25	16	16				D2570	BUSHINGS
26	8	8				MS21042L4	NUT (OR MS21042-4)
27	8	8				AN6-12A	BOLT
28	8	8				NAS1149D0668J	WASHER (AN960JD616)
29	16	16				AN4-6A	BOLT
30	32	32				NAS1149D0463J	WASHER (AN960JD416)
31	16	16				MS21042L4	NUT (OR MS21042-4)
32	4	4				D2747	SET SCREW
33	2	2				D3533-1	SET SCREW
40	1	1				D3407-041	TOW RING (REPLACES D2968-041)
41	1	1				D3456-1	WASHER
43	1	1				MS21043-4	NUT
44	2	2				D3417-5	WASHER
50					1	D3405-041	LUG ASSEMBLY (REPLACES D2736-1)
51					1	D3405-043	LUG ASSEMBLY (REPLACES D2736-3)
52					4	AN4C46A	BOLT
53					8	D2570	BUSHING
54					4	MS21043-4	NUT (OR MS21042-4)
60	2	2				D2876	SADDLE SPACER
61	2	2				D2877	SADDLE SPACER

*DENOTES THAT PART IS INCLUDED WITH D2580-041/-045 ASSEMBLY ABOVE

• COPYRIGHT © 1996 BY DART AEROSPACE LTD. •
 THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED
 OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: G

Date: 11.06.24